



U.S. Department
of Transportation

**Federal Aviation
Administration**

CE-06-46R1
September 18, 2006

SPECIAL AIRWORTHINESS INFORMATION BULLETIN

Aircraft Certification Service
Washington, DC

<http://www.faa.gov/aircraft/safety/alerts/SAIB>

This is information only. Recommendations aren't mandatory.

Introduction

This document revises Special Airworthiness Information Bulletin (SAIB) CE-06-46, dated May 24, 2006, to include the following Cessna make and models: **150, 152, 172, 172R, 172S, 172RG, 177, 177RG, 180, 182, 182S, R182, T182, 185, 206, T206, 208, 210, T210, T303, 310, 335, 340, 402, 404, 414, 421, 425, and 441.** SAIB CE-06-46 describes a discrepancy with Emergency Locator Transmitter (ELT) placard, provided by Cessna Aircraft Company, part number 1205085-2.

This SAIB revision corrects the applicable Cessna models and adds the part numbers of the placard (table 1). All other information remains the same.

Background

The routine surveillance of a Cessna Model 152 discovered that the ELT placard was wearing off

the panel. The operator's certified technician ordered a new ELT placard; part number 1205085-2, from Cessna, the technician noticed that the new placard references the wrong FAA regulation. The placard he ordered reads "EMERGENCY LOCATOR TRANSMITTER INSTALLED BEHIND THIS COVER MUST BE SERVICED IN ACCORDANCE WITH FAR PART 91.52." FAA regulation 91.52 no longer exist, and has been superseded by 14 CFR Part 91.207.

Cessna has removed the old placard from its inventory, and is in the process of producing a new placard. The new placard will read "**EMERGENCY LOCATOR TRANSMITTER INSTALLED BEHIND THIS COVER. MUST BE SERVICED IN ACCORDANCE WITH 14 CFR Part 91.207.**" The new placard part numbers are referenced in the table below. Cessna will also revise their maintenance manuals and parts catalogs at their next scheduled revision.

Table 1

Models	Current Placard P/N	Previous P/N	Original P/N
150, 152, 172, 172RG, 177, 177RG, 180, 182, R182, T182, 185, 208, 210, T210, T303, 310, 340, 402, 414, 421	1205085-10	1205085-3	1205085-1
150, 152, 172, 172RG, 177, 177RG	1205085-9	N/A	1205085-2
208	1205085-10	N/A	1205085-3
restart 172R	1205085-11	1205085-4	1205085-3
restart 182S	1205085-11	1205085-4	1205085-3
restart 206, T206, 172, 172S, 182, T182	1205085-11	N/A	1205085-4
restart 206, T206, 172, 172S, 182, T182	1205085-12	N/A	1205085-7
414, 421, 425, 441	1205085-13	N/A	5700181-11
310, 340, 402, 404, 414, 421	1205085-14	N/A	9754037-31
335, 340	1205085-15	N/A	5300181-94

Recommendation

The FAA recommends you inspect your airplane, and ensure you have the correct regulation referenced on the ELT placard.

For Further Information Contact

Jose R. Flores, Aerospace Engineer, FAA
Wichita Aircraft Certification Office, 1801
Airport Rd, Room 100, Wichita, Kansas, 67209;
phone (316) 946-4133; email:
jose.r.flores@faa.gov

To obtain the placard or service information referenced in this SAIB, contact the Cessna Aircraft Company, Product Support, P.O. Box 7706, Wichita, Kansas 67277-7706; phone: (316) 517-5800; fax: (316) 942-9006.